


WIRING INFORMATION

- M12x1 Eurofast -



Output	Pin 1	Pin 2	Pin 3	Pin 4
mV (4-wire)	+V	+Signal	-Signal	Ground
Voltage (3-wire)	+V	N/A	Ground	Signal
4-20mA (2-wire)	+V	N/A	-V	N/A

+V	Supply Voltage
-V	4-20mA Signal/Electrical Ground
Ground	Voltage Electrical Ground
Signal	Voltage Output Signal
N/A	Not Applicable